



the gpaa

Department:  
Government Pensions Administration Agency  
REPUBLIC OF SOUTH AFRICA

## TENDER - TECHNICAL QUESTIONS

| No | Question   | Answer   |
|----|--|--|
| 1. | On page 38-39, the tender specifies 4 x 3850 switches, with the next item being 4 x 10G transceivers. It is assumed that these transceivers will be utilized on the 3850 platform – yet no 10G network module is specified. Should “C3850-NM-2-10G” be included in the bill of material? | The 4 X 3850 switches to be procured are for the Regional offices, these are small user sites with no more than 14 users per office as such we won't need the 4 X 10G transceivers that is an error on our part please ignore it |
| 2. | On page 43 item “UCSS-U-VMW-FND-3-1” is only specified for 36 months – whereas the rest of the kit requires 60 months. Is this correct?  | Adjust to 60 months  |
| 3. | On page 43 item “UCSS-U-UWL-PRO-3-1” is only specified for 36 months – whereas the rest of the kit requires 60 months. Is this correct?  | Adjust to 60 months  |

| <b>No</b> | <b>Question</b>  | <b>Answer</b>       |
|-----------|--|---------------------|
| 4.        | On page 44 item "CON-SNT-WS-C384PS" is only specified for 12 months – whereas the rest of the kit requires 60 months. Is this correct? | Adjust to 60 months |
| 5.        | On page 44 item "CON-SNT-2901CMST" is only specified for 12 months – whereas the rest of the kit requires 60 months. Is this correct?  | Adjust to 60 months |